Date: Thu, 25 Mar 93 04:30:03 PST

From: Packet-Radio Mailing List and Newsgroup <packet-radio@ucsd.edu>

Errors-To: Packet-Radio-Errors@UCSD.Edu

Reply-To: Packet-Radio@UCSD.Edu

Precedence: Bulk

Subject: Packet-Radio Digest V93 #78

To: packet-radio

Packet-Radio Digest Thu, 25 Mar 93 Volume 93 : Issue 78

Today's Topics:

Baycom Schematic Looking for TheFirmware Majid... Delco... PMP Help (2 msgs) NOS Converse Server on 4.3BSD? Returned mail: Host unknown

Send Replies or notes for publication to: <Packet-Radio@UCSD.Edu> Send subscription requests to: <Packet-Radio-REQUEST@UCSD.Edu> Problems you can't solve otherwise to brian@ucsd.edu.

Archives of past issues of the Packet-Radio Digest are available (by FTP only) from UCSD.Edu in directory "mailarchives/packet-radio".

We trust that readers are intelligent enough to realize that all text herein consists of personal comments and does not represent the official policies or positions of any party. Your mileage may vary. So there.

Date: Wed, 24 Mar 1993 22:06:01 GMT

From: news.acns.nwu.edu!casbah.acns.nwu.edu!lapin@network.UCSD.EDU

Subject: Baycom Schematic To: packet-radio@ucsd.edu

Regarding the Baycom schematic that I posted earlier, some errors have been pointed out to me.

The schematic says: Sheet 1 of 2 but there is no second schematic page (and nothing is missing). I guess that the parts list counts as page 2.

The schematic has R2 listed twice and no R3.

If the real R2 is next to D2 and the real R3 is next to D3, then the value of R3 listed in the parts list should be 100k and not 2.2k.

Also, I tried the audio muting circuit that is an add on in the schematic "for FT470 to silence" and it didn't work well. The design without this works just fine with my FT470 so I didn't worry about it.

As I said before, I don't like this design that uses TTL levels to drive RS232 lines so I changed it. Therefore, I can make no guarantees about how it works. The design that I used, which was modified from this, works wonderfully!

This is a good way to get into packet and I have found that it is all that I need.

Greg Lapin KD9AZ glapin@nwu.edu

PS. Ken, I would have emailed these changes to you but I lost your email address. Sorry.

Date: 22 Mar 93 11:29:30 -0600

From: rcwusr.bp.com!lausts@uunet.uu.net

Subject: Looking for TheFirmware

To: packet-radio@ucsd.edu

I am looking for a FTP site with the code for Nord<>Links TheFirmware. I have checked ucsd.edu and tomcat.gsfc.nasa.gov without success. The latest posting for the packet BBS system discusses a version 2.4c. This firmware is for a TNC2 and is an enhancement for WASDED EPROM.

Thanks
Tom KH6ILT
laus@bpolr1.dnet.bp.com

Date: Wed, 24 Mar 1993 16:35:50 GMT

From: swrinde!gatech!howland.reston.ans.net!ux1.cso.uiuc.edu!news.cso.uiuc.edu!

uxa.cso.uiuc.edu!btbg1194@network.UCSD.EDU

Subject: Majid... Delco... PMP Help

To: packet-radio@ucsd.edu

Date: Wed, 24 Mar 1993 21:31:18 GMT

From: usc!howland.reston.ans.net!newsserver.jvnc.net!siemens!siemens.com!

dep@network.UCSD.EDU

Subject: Majid... Delco... PMP Help

To: packet-radio@ucsd.edu

I am having trouble finding a circuit diagram and a parts list for the poor mans packet (PMP). Does anyone know where I can find this?

Thanks in advance

Dave Post WA2QIK dep@siemens.com

Date: Thu, 25 Mar 1993 03:22:49 GMT

From: munnari.oz.au!newshost.anu.edu.au!sserve!csadfa.cs.adfa.oz.au!

wkt@uunet.uu.net

Subject: NOS Converse Server on 4.3BSD?

To: packet-radio@ucsd.edu

Can anybody tell me if the converse service available under newer versions of NOS has been ported to 4.3BSD as a standalone program, and if so where I can pick up the source code for it.

Many thanks,

Warren vk1xwt

Date: Wed, 24 Mar 1993 10:30:02 -0600

From: Mail Delivery Subsystem <MAILER-DAEMON@uxc.cso.uiuc.edu>

Subject: Returned mail: Host unknown

To: btbg1194@uxa.cso.uiuc.edu

---- Transcript of session follows -----

554 <c23mal@kocrsv01.delcolect.com>... 550 Host unknown (Authoritative answer from name server)

---- Recipients of this delivery -----

Bounced, cannot deliver:

<c23mal@kocrsv01.delcolect.com>

----- Unsent message follows -----Date: Wed, 24 Mar 1993 10:28:56 -0600

From: Bradley T Banko btbg1194@uxa.cso.uiuc.edu Message-Id: <199303241628.AA09677@uxa.cso.uiuc.edu>

```
To: c23mal@kocrsv01.delcolect.com
Subject: Re: PMP Transtmit Problem.
Newsgroups: rec.radio.amateur.packet
In-Reply-To: <1993Mar22.223120.27418@kocrsv01.delcoelect.com>
Organization: University of Illinois at Urbana
Cc:
In article <1993Mar22.223120.27418@kocrsv01.delcoelect.com> you write:
>I am having setup problems on transmit for PMP.
>The PMP works great on recieve but the transmitted
>packets seems to be ignored by other TNC's.
Are you seeing that the modem is triggering the PTT on your radio?
Have you gotten a hold of another radio to use to listen to your
packets to see if the modulation sounds ok?
How far from your station are the other stations? What type of antenna
are you running? What power are you transmitting at? etc.?
>
>I have tried this system with three computers, with the
>same results.
>Any help will be greatly appreciated.
>Majid A. Lodhi
                            INTERNET: c23mal@kocrsv01.delcoelect.com
                             UUCP: deaes!c23mal
>Project Engineer
>Delco Electronics
                            PHONE:
                                      (317) 451-5451
>Kokomo, IN 46904
                             GMNET: (8) 322-5451
KB8CNE, Brad Banko
Brad Banko; Dept of Physics; U of Illinois; b-banko@uiuc.edu
______
See one. Do one. Teach one.
                                   73 de kb8cne @ n9lnq.il
Brad Banko; Dept of Physics; U of Illinois; b-banko@uiuc.edu
______
See one. Do one. Teach one.
                            73 de kb8cne @ n9lnq.il
_____
```

Date: Wed, 24 Mar 1993 13:42:16 GMT

From: usc!howland.reston.ans.net!gatech!kd4nc!ke4zv!gary@network.UCSD.EDU To: packet-radio@ucsd.edu

References <1993Mar19.161346.24177@ve6mgs.ampr.org>, <1993Mar20.152529.17081@ke4zv.uucp>, <11803@prijat.cs.uofs.edu>

Reply-To: gary@ke4zv.UUCP (Gary Coffman)

Subject: Re: Packet Radio via CB????

In article <11803@prijat.cs.uofs.edu> bill@triangle.cs.uofs.edu (Bill Gunshannon)
writes:

>In article <1993Mar20.152529.17081@ke4zv.uucp>, gary@ke4zv.uucp (Gary Coffman) writes:

>|> I have no doubt that it would also work on Class D CB, though it is
>|> illegal under *US* regulations to do so *here*.

>How can anything be considered "illegal" on a service that has no enforcement >until it interferes with another service?? How could packet radio be construed >as anything other than another one of the many noise makers that have been in >vogue on 27 Mhz for a number of years??

While enforcement *is* lax, that doesn't change the fact that it is illegal. CB is a garbage band primarily because people don't follow the rules. In most social activities, this rule following is by consensus of the majority with only a few outlaws that require police action. This allows for a stable and friendly group interaction. On the CB band, the outlaws are the majority. Only fascist application of police power can suppress a majority, and that hasn't happened yet.

Gary

- -

Gary Coffman KE4ZV | You make it, | gatech!wa4mei!ke4zv!gary
Destructive Testing Systems | we break it. | uunet!rsiatl!ke4zv!gary
534 Shannon Way | Guaranteed! | emory!kd4nc!ke4zv!gary
Lawrenceville, GA 30244 | |

End of Packet-Radio Digest V93 #78